Dental Imaging Software

DIS Suite 1.14.0 / Drivers DVD 1.14.0

Tech News

TN#224

Date:
November 18th 2015

Product:
Dental Imaging Software

Document Reference #:
TN224_DIS Suite 1.14.0_EN

Validity:
NA

Distribution:
External
Internal

Writer:
Rachid Jdiaoui

Contact:

The new release of Dental Imaging Software is distributed on DIS Suite 1.14.0 / Drivers DVD 1.14.0.
It replaces previous versions of DIS Suite 1.13.0 / Drivers DVD 1.13.0.
Both versions Suite & Drivers have to be updated





Download: click here

Available on each product tab

*Note: Both **DIS and TW** (Japan only) versions on infotec website – menu Download.*

This Tech News covers the following points:

- New features
- Component versions
- Compatibility matrix

Tech News

DIS SUITE DVD

- **New 3D Viewer version 3.5.18**:

  - Windows 10 Support
  - Custom rendering presets (Japan only)
  - Default thickness for 2D views
  - Add new options to the list of supported slice thickness with Volume convertor
  - Display of the patient sex and date of birth

Drivers DVD

- **RVG driver version 4.6.9.0-C:**

  - Bug fix: USB 3 instability
  - Windows 10 support
  - RVG Connect for CS 6200: Refer to Product News #376



- **CS 9300 driver 2.4.3.0-N / CS 9300S driver 1.1.5.0-N:**

  - New DIN standard support in the service tools
  - Windows Seven 32 bits compatibility
  - Improvement on CS 9300 FOV 5X5 reconstruction algorithm
  - QAT artifact checking during QAT 3D control in service tools

- **CS 1200/1500/1600 camera driver 31.1.29**:

  - Windows 10 support
  - Fixed FMS out of order issue by update plug-in software

- **CS 8000Ethernet driver 5.0.2.29-B** :
    - Driver now available on DVD Drivers

- **CS 8100 Family:**



The CS 8100/8100 3D/8100SC drivers are not included in the DVD Drivers. Each driver will be included in the product packaging.
Please refer to the following Product News & Technews:

- CS 8100 => TN#225
- CS 8100 3D => TN#226
- CS 8100SC => TN#227
- Product News => PN #386

➢ Component versions

Disk 1/2 DIS Suite v.1.14.0	***Products***	DIS 6 Imaging_Software	**6.14.7.3**
		CS 3D Imaging Software	3.5.18
		CS Restore	1.6.6-B
	Add-ons	CS Film Composer	3.5.4
		Quick Burn	1.4.0.0-C
		Volume Convertor	1.1.3
		CS Mesh Converter	1.0.6
		Ceph Tracing	**1.0.23.0-B**
		RecBase	1.2.0.5-D
		CS Licensing	1.0.4.8
		CS Model	1.5.1.0
		TaskQueue DataBaseCleaner	1.0.0.0
		DicomTools	1.0.127
		DicomViewer	1.0.123.936
		DICOM Printer Driver	2.0.0.17
		DICOM Printer Driver 64 bits	2.0.0.18
		DotNet2.0	2.0.50727.42
		DISDemoImageDatabase	1.5
	DPMS integration	CS Link	5.0.10.8-A
		VDDS media Interface	1.11.0.2

Disk 2/2 Drivers v.1.14.0	***Drivers***	Intra-oral cameras	Camera STV	1.3.61.0
			CS1x00 Light Edition Wizard	3.1.29.0
		RVG sensors	RVG	4.5.100.0
			CS 8000 E	5.0.2.29-B
			CS 9000	5.4.5.0-C
			CS 9300	2.4.3.0-N
			CS 9300 Select	1.1.5.0-N
			CS 9300 Demo Files	1.0.12.0
			CS 9300 Select Demo Files	1.0.9.0
	Miscellaneous	TaskQueue DataBaseCleaner		1.0.0.0
		DicomTools		1.0.127.936
		DicomViewer		0.0.0.1
		CS 9300 Masking file patch for PCIExpress		1.0
		CSDIT drivers		2.1.1.1

© Carestream Health, Inc. 2013

❖ Not included in the Drivers DVD (direct download available on Infotec website)

Drivers	Extra-oral	CS 9500	5.0.7
		CS 8000 PCI	5.0.2.29-B
		CS 8100 2D	0.2.16.1-B
		CS 8100 3D	1.0.19.0-D
		CS 8100SC	0.2.202.10
Drivers	CR systems	CR	1.3.44.9
	CS Solutions	CS 3000	0.2.0.4
		CS 3500	1.2.0.10

© Carestream Health, Inc. 2013

➢ Compatibility matrix

This section specifies the minimum operative system requirements applicable to the imaging software and associated drivers delivered on DIS Suite 1.14.0 / Drivers DVD 1.14.0 and other compatible systems. It is mandatory to check that the O/S system configuration is compatible with the O/S system requirements. If necessary, you must update the O/S system. *WIP: Work In Progress

Application	XP 32 bit	XP 64 bit	Vista 32 bit	Vista 64 bit	Win7 32 bit	Win7 64 bit	Win8 64 bit	Win 8.1 64 bit	Win 10 64 bit	Server 2003	Server 2008	Server 2008 R2 64bit
DIS	N	N	N	N	Y	Y	Y	Y	Y	N	Y	Y
CS 3D Imaging	Y	N	Y	N	Y	Y	Y	Y	Y	N	N	N
CS Restore	N	N	N	N	Y	Y	Y	Y	Y	N	N	N
CS Model	N	N	N	N	Y	Y	Y	Y	Y	N	N	N
RVG UI, 5000 / 6000	Y	N	Y	N	Y	Y	Y	Y	N	N	N	N
RVG 5100 / 6100 / 6500	Y	N	Y	N	Y	Y	Y	Y	Y	N	N	N
RVG 5200 / 6200	N	N	N	N	N	Y	Y	Y	Y	N	N	N
CS 8000 Family PCI	Y	N	Y	N	Y	N	N	N	N	N	N	N
CS 8000 Family Ethernet	Y	N	Y	N	Y	Y	Y	Y	WIP* Dec. 2015	N	N	N
CS 8100 Pan/3D	N	N	N	N	N	Y	Y	Y	Y	N	N	N
CS 9000 Pan/Ceph/3D	Y	N	Y	N	Y	Y	Y	Y	WIP* Dec. 2015	N	N	N
CS 9300 Pan/Ceph/3D	N	N	N	N	Y	Y	Y	Y	WIP*	N	N	N
CS 9300 Select Pan/Ceph/3D	N	N	N	N	Y	Y	Y	Y	WIP*	N	N	N
9500 3D	Y	N	Y	N	Y	Y	N	N	N	N	N	N
STV/1000 Camera	Y	N	Y	N	Y	N	N	N	N	N	N	N
OEM Camera	Y	N	Y	N	Y	N	N	N	N	N	N	N
CS 1200/1500/1600 Camera	Y	N	Y	N	Y	Y	Y	Y	WIP* Dec. 2015	N	N	N

CS 3500 3D IO scanner	N	N	N	N	Y	Y	Y	Y	WIP* Dec. 2015	N	N	N
CS 3000 Milling	N	N	N	N	N	Y	Y	Y	WIP*Dec. 2015	N	N	N
CS 7400	Y	N	Y	N	Y	Y	N	N	WIP* Dec. 2015	N	N	N
CS 7600	Y	N	Y	N	Y	Y	Y	Y	WIP* Dec. 2015	N	N	N
CS 7200	N	N	N	N	Y	Y	Y	Y	WIP* Dec. 2015	N	N	N